


SpotSee QR Cloud User Manual - Temperature Products

New User Set Up

Each bag, box, or pack of QR enabled products has a registration code on the label. Users can either scan the QR code or follow the link to register for their cloud account.

Scan QR code or follow link



Create Account


One person per organization should create an account from the label. That person can then add users to the account with various permissions. The sensors are unique to the cloud which they are added to so it is important to have all persons who need access within the same cloud. An email will be sent to the user with a temporary password.

A screenshot of the SpotSee Account Registration web form. The form has a blue header with the SpotSee logo and a tab labeled 'ACCOUNT REGISTRATION'. The form fields include: 'Account / Company Name' (with a pencil icon), 'Username' (with a person icon), 'Full Name' (with a pencil icon), and 'Email' (with an envelope icon). Below the fields is a checkbox for 'I agree to the SpotSee Terms & Conditions.' and a link to 'Sign In.' for existing users. A blue 'Register' button is at the bottom right. The footer contains the copyright notice '© Copyright 2024-10-15. All Rights Reserved.'

SpotSee QR Cloud User Manual - Temperature Products

Login with Temporary Password


Users can log in at <https://qr.spotsee.io>



The image shows the SpotSee login interface. At the top left is the SpotSee logo. In the top right corner, there is a blue button with a person icon and the text "SIGN IN". Below the logo is a white login form. The form has two input fields: "Username" and "Password". To the right of the Password field is a link that says "Reset Password?". Below the Password field is a checkbox labeled "Remember Me" and a blue button labeled "Sign In". At the bottom of the form, there is a copyright notice: "© Copyright 2024-11-04. All Rights Reserved."

Finish Profile and Password Set Up

After logging in with the temporary password, the user will be prompted to change their password. Each user must have a unique username and a password that meets system requirements.




The image shows the "Update Profile" form. At the top, there is a blue link that says "Update Profile". Below this is a red banner with the text "Please set your password to proceed". The form contains several input fields: "Username" (with a person icon), "Full Name" (with a pencil icon), "Email" (with an envelope icon), "Temperature Scale" (a dropdown menu currently showing "Celsius (°C)"), "Date Format" (a dropdown menu currently showing "mm/dd/yyyy (04/04/2024)"), and "Time Zone" (a dropdown menu currently showing "(UTC -05:00) Eastern Time (US & Canada), Bogota, Lima"). Below these fields is a checkbox labeled "Update Password?" which is checked. At the bottom, there is a "Password" field (with a lock icon and a toggle for visibility) and a button labeled "Generate Password". Below the password field, there is a note: "Minimum eight (8) characters in length, at least two (2) complexity controls (uppercase letter, lowercase letter, special character), no reuse of previous six (6) passwords".

SpotSee QR Cloud User Manual - Temperature Products

Returning User Sign On


After a username and password have been established, users can sign in by navigating to <https://qr.spotsee.io> and signing in.



The image shows the SpotSee login interface. At the top left is the SpotSee logo. To its right is a blue button with a person icon and the text "SIGN IN". Below the logo is a white login box. Inside the box, there is a "Username" label above a text input field with a person icon on the right. Below that is a "Password" label above a text input field with a lock icon on the right. To the right of the password field is a blue link that says "Reset Password?". Below the password field is a checkbox labeled "Remember Me". To the right of the checkbox is a blue button that says "Sign In". At the bottom of the login box, there is a copyright notice: "© Copyright 2024-11-04. All Rights Reserved."

Dashboard


Upon signing in, users will access their Dashboard which provides an overview of the Sensors Scanned, Excursions Detected, Sensors Remaining, Allocated Shipments, temperature excursion heat map and Temperature Shipments scan data by month.



SpotSee QR Cloud User Manual - Temperature Products

Navigation Bar

When the cursor is positioned over the left side of the **Dashboard**, the **Navigation Bar** will appear. This menu allows the user to choose the appropriate views for information like the Dashboard (Home), QR Products, and Admin, consisting of Users and Audit Log.



Temperature Shipments

Use the **Navigation Bar** to enter the **Temperature Shipments** screen by hovering over the QR Products drop down, the user will display summary information for each of their sensors.

Temp Range	Sensor ID	Shipment ID	Shipment Condition	Sensor Image	Location	Location Accuracy	Last Scan	History
8°C/46°F, 8 hr	2222nrvHz7x8		✗	View Image	View Map	High	2025-11-16 05:01:45	History
-18°C/0°F, 12 hr	2222mWWB8x8	AirwayBill 123	✗	View Image	View Map	High	2025-10-13 05:08:56	History
-18°C/0°F, 12 hr	2222mWWBh3x6	Airway Bill 123	✗	View Image	View Map	High	2025-10-13 04:17:10	History
-18°C/0°F, 12 hr	2222n6Bn4w4		✓	View Image	View Map	High	2025-10-12 08:20:18	History
8°C/46°F, 8 hr	2222nrvK94d4		✓	View Image	View Map	High	2025-08-29 06:45:46	History
8°C/46°F, 48 hr	2222nrvHrP7s		✓	View Image	View Map	High	2025-08-27 12:17:02	History
8°C/46°F, 48 hr	2222nrvH43G7		✓	View Image	View Map	High	2025-08-26 16:47:07	History
8°C/46°F, 48 hr	2222JWYK9C24R	Lima Expalmentaria	✓	View Image	View Map	High	2025-08-23 10:08:39	History
8°C/46°F, 8 hr	2222nrvS73a6		✓	View Image	View Map	High	2025-08-12 06:39:24	History
8°C/46°F, 8 hr	2222p99xW7m7		✓	View Image		User declined	2025-08-11 10:18:46	History

SpotSee QR Cloud User Manual - Temperature Products

Below are definitions for the fields and buttons found on the Temperature Shipments screen:

Temp Range: The temperature and run out time associated with a particular sensor.

Sensor I.D.: Unique identification code for a particular Temperature sensor. This can be found by scanning the QR code on the front of a sensor.

Shipment I.D.: User fillable field for inserting an order number, tracking information, or other identifying descriptor that a shipper can use to tie to a sensor I.D. Click icon to bring up fillable window.

Shipment I.D 22223WTVJ9A846




Save
Close

Shipment I.D 22223WTVJ9A846




Save
Close

Shipment Condition: Condition read-out status based on the last scan:



No condition recorded




Shipment OK, no temperature excursion detected




Temperature Excursion Detected

SpotSee QR Cloud User Manual - Temperature Products

Sensor Image: Image of the last scan taken... this is what the end user saw. Clicking on the **View Image** text will open a separate browser window displaying the image.



Location: Location of last scan based on scanning device (cell phone) connectivity. Clicking on the **View Map** text will open a separate browser window displaying the map.



SpotSee QR Cloud User Manual - Temperature Products

Last Scan: Time and date stamp of last scan.

Location Accuracy: High (<100 meters), Medium (between 100 and 1000 meters), and Low (>1000 meters).

History: By clicking on the **below icon under the History column** users can view detailed scan history for specific sensors. Information available includes condition, a scan image, location, and time and date of a particular sensor I.D.

Scan History 22223WTVHHB6MH

#	Shipment Condition	Sensor Image	Location	Location Accuracy	Scan Date
5	✓	View Image	View Map	High	2024-09-30 14:14:49
4	✓	View Image	View Map	High	2024-09-30 05:58:33
3	✓	View Image	View Map	High	2024-09-29 07:16:29
2	✓	View Image	View Map	High	2024-09-28 19:03:24
1	✓	View Image	View Map	High	2024-09-24 07:07:30

Map Satellite

Google

Keyboard shortcuts | Map data ©2025 Terms

CLOSE

SpotSee QR Cloud User Manual - Temperature Products

Adding Sensors to Cloud

When first receiving QR enabled sensors, locate the label on the unit pack.

Mobile Phone:

- Scan the QR code on bag label with your mobile device

Returning Users:

- Select “Sign In” option at registration page, navigate to the Temperature Shipments page, and select “Add Sensors” located in the top right corner
- Type or scan the bag ID(s) associated with the bags of sensors you need to add to your cloud

New Users:

- Register for cloud account and follow all prompts. Sensors will be auto added to account upon completing registration





Computer:

Returning Users:


- Log into qr.spotsee.io
- Navigate to the Temperature Shipments page, and select “Add Sensors” located in the top right corner
- Type or scan the bag ID(s) associated with the bags of sensors you need to add to your cloud

New Users:

- Type QR code URL into browser to register for cloud account and follow all prompts
- Repeat steps 2 and 3 from “Returning Users” section above to add sensors to cloud




SpotSee QR Cloud User Manual - Temperature Products



Adding A User

Hover over the **Navigation Bar** to display the Admin selection. Select the **drop down on the Admin selection** to make visible Users and Audit Log. Select **Users**.

All Active Users and Removed Users are displayed on this page. Select **+Add User** in the top right corner to begin steps of adding a new user.



After completing the required fillable fields, select the **User Role** for the new user.

User Role

USER

▼

USER_ADMIN: Full access to system

USER: Limited access (unable to manage users/api users or view audit log)

API_USER: API access only

✓ Submit

SpotSee QR Cloud User Manual - Temperature Products

Audit Log

Hover over the **Navigation Bar** to display the Admin selection. Select the **drop down on the Admin selection** to make visible Users and Audit Log. Select **Audit Log**.

Audit Log				
User	View All	Date	2024-10-28 to 2024-11-04	
10 records per page Search				
Name	Section	Action	Data	Audit Date
Mason McWilliams	Reporting	Create	ReportType: Sensors, BagID: 0, Status: -1, ProductCode: , DateRange: 2024-10-04 00:00:00-2024-11-04 ...	2024-11-04 14:26:58
Mason McWilliams	QRShipment	Create	SensorID: 22223WTVJ9A846, ShipmentID: Order#378HXW9	2024-11-04 14:13:40
Mason McWilliams	Reporting	Create	ReportType: Shipments, DateRange: 2024-01-01 00:00:00-2024-10-31 23:59:59	2024-10-31 13:48:45
Mason McWilliams	Reporting	Create	ReportType: SensorHistory, SensorID: 22223WTVK9C24R	2024-10-30 14:11:22
Mason McWilliams	QRBag	Create	Allocate Bag, ID: 222222BpR4H8GT	2024-10-30 14:08:26
Mason McWilliams	Users	Modify	Username: TWilliams -> TWilliams, Full Name: Tim -> Tim Williams, Email: twilliams@spotsee.io -> twl...	2024-10-28 20:46:43
Mason McWilliams	Users	Create	Username: TWilliams, Full Name: Tim, Email: twilliams@spotsee.io, Temperature Scale: C, Date Format:...	2024-10-28 20:46:34

The Audit Log captures the creation, deletion, and modification of records within the SpotSee Cloud.

Exporting Data

Located throughout the cloud are various opportunities to export data including the Dashboard (Home), Temperature Shipments page, within the modal window on the scan history column, and the audit log.

Look for these icons:



Report Requested

Your report has been created, please click the link below to download your report

[Download Report](#)

OK