

TiltWatch XTR Mounting Instructions

1. Peel the adhesive liner from the back of the TiltWatch XTR while holding it in an upright position.
2. Place the TiltWatch XTR in a visible location on the shipping container.
3. Press the TiltWatch XTR firmly in the center and around the edges to ensure strong adhesion to the container.



**Complete instructions are
available at www.spotsee.io**